



MAGNETIC HILL ZOO OTTER POOL COATING

LOCATION: MONCTON NB

CONSTRUCTION: AUS WAS TASKED APPLYING A NEW COATING TO THE OTTER POOL AND STOPPING THE POOL FROM CONTINUING TO LEAK WATER. WITH THE POOL DRAINED A CONCRETE REPAIR WAS PERFORM AT THE AREA OF THE LEAK. THE WALLS AND FLOOR WERE SANDBLASTED TO BARE CONCRETE AND AN EPOXY COATING WAS APPLIED.



OWNER: CITY OF MONCTON
JOB REFERENCE: AUS #J-1-27
DATE: AUGUST 2020

UNIQUENESS: THE WORK WAS COMPLETED WHILE THE ZOO REMAINED OPEN TO VISITORS. EXTRA PROTECTION WAS IMPLEMENTED TO ENSURE THE SURROUNDING PUBLICS SAFETY.



ATLANTIC UNDERGROUND SERVICES LTD.

425 PINE GLEN RD • RIVERVIEW, N.B. • E1B 4J8 • (506)387-8160

INFO@AUSLTD.COM