



POOL COATING AT MONCTON CITY HALL

LOCATION: MONCTON, NB

CONSTRUCTION: AUS WAS TASKED WITH REMOVING AND REPLACING THE DETERIORATING COATING IN THE WATER FOUNTAIN



LOCATED INFRONT OF THE MONCTON CITY HALL. THE REMOVAL OF THE COATING WAS DONE WITH A COMBINATION OF SHOT BLASTING AND WET SANDBLASTING. AN ECTOFLEX COATING WAS THEN BRUSH APPLIED. THE RESULT WAS A WATERTIGHT SOLUTION THAT VISIBLY APPEALING.



OWNER: CITY OF
MONCTON

JOB REFEREANCE: 73997

DATE: JUNE 2019



UNIQUENESS: THE LOCATION OF THE WATER FOUNTAIN WAS A HIGH FOOT TRAFFIC AREA THAT REQUIRED EXTRA PROTECTION TO ENSURE PUBLIC SAFETY. FENCING AND MESH WERE INSTALLED TO CONTAIN ANY FLYING DEBRIS AND WET SANDBLASTING WAS CONDUCTED TO ENSURE NO DUST WAS MADE.



ATLANTIC UNDERGROUND SERVICES LTD.

425 PINE GLEN RD • RIVERVIEW, N.B. • E1B 4J8 • (506)387-8160

INFO@AUSLTD.COM